

FERNDALE BOROUGH  
PRESSURE TESTING UPDATE  
February 9, 2015

1. Pressure Testing Inspections

- 464 inspections complete
  - Entire System Tested – 195
  - Tested to inside Foundation – 97
  - Outside only tested – 172
  - Storm Verification Required – 3  
(\* storm verification required by property owners where Borough was responsible for connection or property was connected during main line construction.)
  - Ferndale Ave – sewer line was not replaced – no viewports. Will contact property owners for storm verification
  - Tillman Ave – will send letters when City accepts line from contractor

2. Items for Discussion

- Lateral Issues
  - 540 Glenwood Ave – lateral not deep enough
  - 557-561 Ferndale Ave – need easement – Penn Machine willing to give easement completed drawing – will help coordinate with solicitor and property owner
  - Coordination with CJL
- Miscellaneous Issues
  - Tillman Ave –Ferndale Customers
  - Stoneycreek Twp – capacity charge, flow monitoring point?
- Ferndale Borough Responsible to install laterals
  - 211 Summit Avenue – Deborah L. Kralik
- Tie in connections to complete Sewer Separation
  - Properties outside of Ferndale that flows through Borough